

This anomaly list describes the known bugs, anomalies, and workarounds for the [ADuC7060/ADuC7061](#) MicroConverter® Revision D silicon. The anomalies listed apply to all ADuC7060/ADuC7061 packaged material that is branded as follows:

First Line ADuC7060/ADuC7061

Third Line D30 or newer (revision identifier)

Analog Devices, Inc., is committed, through future silicon revisions, to continuously improve silicon functionality. Analog Devices tries to ensure that these future silicon revisions remain compatible with your present software/systems by implementing the recommended workarounds outlined here.

### ADuC7060/ADuC7061 FUNCTIONALITY ISSUES

Silicon Revision Identifier	Kernel Revision Identifier	Chip Marking	Silicon Status	Anomaly Sheet	No. of Reported Anomalies
D	0	All silicon branded D30	Release	Rev. A	7

### ADuC7060/ADuC7061 PERFORMANCE ISSUES

Silicon Revision Identifier	Kernel Revision Identifier	Chip Marking	Silicon Status	Anomaly Sheet	No. of Reported Anomalies
D	0	All silicon branded D30	Release	Rev. A	1

### ADuC7060/ADuC7061 SILICON FUTURE ENHANCEMENTS

Silicon Revision Identifier	Kernel Revision Identifier	Chip Marking	Silicon Status	Anomaly Sheet	No. of Reported Anomalies
D	0	All silicon branded D30	Release	Rev. A	1

## ANOMALIES

### ADuC7060/ADuC7061 Functionality Issues

Table 1. External IRQ When Configured as Level Sensitive [er002]

<b>Background</b>	There are four external interrupt sources on the ADuC7060/ADuC7061 parts. These can be configured as edge triggered (rising or falling) or level triggered (active high or active low).
<b>Issue</b>	When any of the external interrupt sources are configured as level triggered, either active high or active low, the external pin must remain at the active level until the program vectors to the interrupt vector handler for that external interrupt. If the external pin is activated, triggering an interrupt, but subsequently goes to an inactive level before the program vectors to the interrupt handler, the appropriate IRQSTA bit for the external interrupt may not be set. This results in the interrupt handler not knowing what interrupt source caused the part to vector to the interrupt vector.
<b>Workaround</b>	Edge triggered interrupts do not have this problem. A fix is pending for this issue.
<b>Related Issues</b>	None.

Table 2. DAC Output Limited to AVDD – 250 mV [er005]

<b>Background</b>	The DAC output range can be configured to four different settings: <ul style="list-style-type: none"><li>• 0 V to <math>V_{REF}</math> (1.2 V) range (internal reference source)</li><li>• VREF– to VREF+</li><li>• ADC5/EXT_REF2IN– to ADC4/EXT_REF2IN+</li><li>• 0 V to AVDD</li></ul>
<b>Issue</b>	The DAC output buffer is limited in the maximum output voltage in that it can drive to AVDD – 250 mV. This is less than the data sheet specification of AVDD.
<b>Workaround</b>	A fix is pending for this issue.
<b>Related Issues</b>	None.

Table 3. Disabling I<sup>2</sup>C Interface in Slave Mode When a Transfer Is in Progress [er006]

<b>Background</b>	Bit 0 (I2CSEN) of the I2CSCON register enables/disables the I <sup>2</sup> C slave interface. Bit 6 (I2CBUSY) of the I2CSSTA register indicates if the I <sup>2</sup> C slave interface is busy or not.
<b>Issue</b>	If I <sup>2</sup> C slave mode is enabled (I2CSCON[0] = 1), and a transfer is in progress with the master, then I2CSCON[0] should not be cleared to 0 to disable the I <sup>2</sup> C slave interface until Bit 6 of I2CSSTA (I2CBUSY, the I <sup>2</sup> C slave busy status bit) is cleared. When I2CSCON[0] is cleared to 0 and the I <sup>2</sup> C slave busy status bit is still set, the ADuC7060/ADuC7061 may drive the SDA pin low indefinitely. When this condition occurs, the ADuC7060/ADuC7061 does not release the SDA unless a hardware reset condition occurs.
<b>Workaround</b>	When disabling I <sup>2</sup> C slave mode by writing to I2CSCON[0], first set Bit 0 (I2CMEN) of the I2CMCON register = 1 to enable master mode. Then disable the slave mode by clearing I2CSCON[0]. Finally, clear I2CMCON[0].
<b>Related Issues</b>	None.

Table 4. Operation of SPI in Slave Mode [er007]

<b>Background</b>	When in SPI slave mode, the ADuC7060/ADuC7061 expects the number of clock pulses from the master to be divisible by 8 when the slave chip select pin ( $\overline{SS}$ ) is active.
<b>Issue</b>	The internal bit shift counter does not reset when the chip select pin is deasserted. If the number of clocks from the master is not divisible by 8 when the chip select ( $\overline{SS}$ ) is active, this can result in incorrect data being received or transmitted by the ADuC7060/ADuC7061 because the internal bit shift counter will not be at 0 for subsequent transfers. The internal bit shift counter for the transmit or receive buffers can only be reset by a hardware, software, or watchdog reset condition.
<b>Workaround</b>	Always ensure that the number of SPI clocks are divisible by 8 when the ADuC7060/ADuC7061 chip select ( $\overline{SS}$ ) is active.
<b>Related Issues</b>	None.

**SECTION 1. ADuC7060/ADuC7061 FUNCTIONALITY ISSUES**

Reference Number	Description	Status
er001	Power-down mode issue	Fixed on Revision C and later silicon
er002	External IRQ when configured as level sensitive	Open
er003	SPI issue in slave mode when the SPI serial clock phase mode bit (SPICH) is set	Fixed on Revision C and later silicon
er004	Primary ADC self-gain calibration mode	Fixed on Revision C and later silicon
er005	DAC output limited to AVDD – 250 mV	Open
er006	Disabling the I <sup>2</sup> C interface in slave mode when a transfer is in progress	Open
er007	Operation of SPI in slave mode	Open

**SECTION 2. ADuC7060/ADuC7061 PERFORMANCE ISSUES**

Reference Number	Description	Status
pr001	DAC relative accuracy when the output range is greater than 0 V to 1.2 V	Fixed on Revision C and later silicon

**SECTION 3. ADuC7060/ADuC7061 SILICON FUTURE ENHANCEMENTS**

Reference Number	Description	Status
fe001	Primary ADC input buffer bypass	Fixed on Revision C and later silicon

# NOTES