

Product Change Notification (PCN)

PCN no.: PCN_081 rev. 1.0	Date: 2013-06-11
Device affected: nRF8001-R2Q32	Device version / Build Code: D
Data sheet references: N/A	Agreement reference: N/A
	Customers reference: N/A

Description of change:	
Minor firmware change adding extra trimming capabilities for Nordic's production flow.	
Configuration ID changed from "0x0015" to "0x0000".	
Impact: Does the change affect <u>product</u> :	
1. Form	<input checked="" type="checkbox"/> No <input type="checkbox"/> Yes – describe:
2. Fit	<input checked="" type="checkbox"/> No <input type="checkbox"/> Yes – describe:
3. Function	<input checked="" type="checkbox"/> No <input type="checkbox"/> Yes – describe:
4. Quality or Reliability	<input checked="" type="checkbox"/> No <input type="checkbox"/> Yes – describe:
Classification of change	<input checked="" type="checkbox"/> Minor <input type="checkbox"/> Major
Reason for change:	
Yield improvements	
Consequences of change:	
None, but customer should allow for both Configuration IDs in applications and/or test software.	
Verification:	
The change is verified according to Nordic Semiconductor standard QA procedures.	
Marking/Shipping labels:	
No changes	
Change active from (date):	Change active from (trace code):
20 th June 2013	1311GT-1312HF, both FWIDs "0x0015" and "0x0000" may occur 1311HG, only FWID "0x0000"
Last time order (date): (optional)	Final shipment date: (optional)
N/A	Existing stock to be depleted
Attachments:	<input checked="" type="checkbox"/> No <input type="checkbox"/> Yes – describe:
Technical contact at Nordic Semiconductor:	Commercial contact at Nordic Semiconductor:
Contact: Analiza Gueta Title: Project Manager e-mail: analiza.gueta@nordicsemi.no	Contact: Thomas Embla Bonnerud Title: Product Manager e-mail: thomas.embla.bonnerud@nordicsemi.no
Authorization for Nordic Semiconductor	
Product Manager	Date: 2013-06-11 Sign: 
Quality Director	Date: 2013-06-11 Sign: 

Please note that all last time buy orders are non-cancellable and non-returnable.